

Solder Gun

SAFETY SUGGESTIONS

1. Always wear approved eye protection.
2. Work in a well-ventilated area and avoid inhaling soldering fumes.
3. Observe all rules for handling *hot* materials.
4. Do not flip excess molten solder off the tip of solder gun. Wipe it off with a piece of steel wool.
5. Do not stand in wet areas while using the solder gun.
6. Never leave the solder gun unattended with the electrical cord plugged in.
7. Always disconnect cord when changing soldering tips.
8. Soldering flux can cause burns. Clean up flux immediately.
9. In case of acid burns, flush immediately with water. (Use baking soda to neutralize acids.)
10. Never use solder gun with worn or exposed wiring or a cracked plastic cover/handle.

